Setronix
desde 1966

**FEBRUARY**
**2027**
**WORKPLACE SAFETY CAMPAIGN**



# MACHINES AND TOOLS

**Check before switching on. Stop if you find a fault.**

## 1. Hazards and risks

**Hazards:** Moving parts, sharp edges, flying debris and energy.

**Risks:** Cuts, crushing, electric shock and eye injuries.

## 2. Before you start


- Check training and suitability for the task.
- Check condition, guards and accessories.
- Read the manual and wear the specified PPE.

## 3. Stop and report

- Missing guards or faulty controls.
- Unusual vibration, noise or overheating.
- Loose workpiece, damaged cable or worn accessory.

## 4. Prepare, use and finish safely

1



**Choose**

Use equipment suited to the task.

2



**Prepare**

Secure the workpiece and organise the area.

3



**Use**

Keep hands away; leave guards in place.

4



**Finish**

Stop and switch off before storing.

## 5. Assess the situation and choose prevention

| Situation | Preventive measure |
|---|---|
| **Workpiece** | Secure it appropriately; do not improvise supports. |
| **Accessory / consumable** | Check compatibility and conditions in the manual. |
| **Moving parts** | Do not remove or bypass safety guards. |
| **Cleaning / clearing jams** | Isolate energy and prevent unexpected start-up. |

**Good practice:** A stop command does not guarantee zero energy. Cleaning, adjustments and clearing jams require suitable isolation and a competent person.

**6. MONTHLY ACTION** Check equipment before use. Report defects and prevent unsafe equipment being used, following the applicable procedure.

**CHECK • KEEP GUARDS IN PLACE • STOP**

ACT: machines and equipment  Good practice: HSE / maintenance

Setronix | February 2027 | Final version 1.0 | 09/10/2026 | Employees using machines and tools | EN